

WASHTENAW COUNTY ROAD COMMISSION

TO: Washtenaw County Board of Road Commissioners

FROM: Roy D. Townsend, P.E.
Managing Director

SUBJECT: Staff Report – 1-8-18 to 1-28-18

DATE: February 6, 2018

TOWNSHIP REPORT

OPERATIONS REPORT

A. Maintenance

Patching of paved roads took place throughout the County. In addition, the following specific maintenance activities were performed in individual townships.

ANN ARBOR TOWNSHIP

- Roadside – Nixon Road

AUGUSTA TOWNSHIP

- Limestone Patch – Arkona Road, Bunton Road, Liss Road, McCrone Road:
103 tons

DEXTER TOWNSHIP

- Fallen Trees – Stofer Road

FREEOM TOWNSHIP

- Drainage and Backslopes – Ernst Road

LIMA TOWNSHIP

- Limestone Patch – Trinkle Road:14 tons

LYNDON TOWNSHIP

- Limestone Patch – Bowdish Road:24 tons

MANCHESTER TOWNSHIP

- Cut Trees – Van Tuyle Road

PITTSFIELD TOWNSHIP

- Culvert Demolition – Bemis Road
- Fallen Trees – Carpenter Road

SHARON TOWNSHIP

- Cut Trees – Sharon Valley Road
- Limestone Patch – Parr Road: 12 tons

YORK TOWNSHIP

- Limestone Patch – Samer Road, S Maple Road: 110 tons

YPSILANTI TOWNSHIP

- Cleaned Drain – Desoto Avenue
- Fallen Limbs – Briarbrook Drive
- Limestone Patch – E Bemis Road: 257 tons
- Remove Guardrail – Canyon Drive, Maulbetsch Street, Stratford Road

WINTER MAINTENANCE

- Crews Responded – 15 times
- Total Salt Used – 6,267 tons
- Total Abrasives Used – 1,588 tons
- Total Brine Used – 12,567 gallons

NORTHEAST SERVICE CENTER UPDATES

Contractors are working on punch list items of work and prepared for the training session on January 18th for WCRC staff. We received our official approval letter from LARA regarding the Fuel Depot.

SHOP REPORT

Shop Repairs

- Tires Repaired – 4 tires
- New Tire Installation – 15
- Vehicles Serviced – 15
- Vehicles Serviced by Suburban Chevrolet – 4
- Work Orders Completed – 33

Equipment Repair

- Truck 117 – Replaced the ignition switch
- Truck 121 – Replaced brakes, ball joints and U-joints
- Truck 219 – Replaced the dump body hydraulic pump
- Truck 315 – Replaced the DEF injection electrical harness
- Truck 333 – Replaced the main hydraulic hose and welded sub-frame cracks
- Truck 344 – Replaced a radiator hose, speedometer senders, and a wheel seal
- Truck 351 – Replaced a drive hub
- Truck 381 – Replaced 2 air bags, the drag link and the back-up alarm
- Truck 396 – Replaced the wiper motor
- Sweeper 1008 – Installed a new battery

BUILDING & GROUNDS REPORT

Yard One

- Recycling
- Snow Removal
- Plumbing Repairs
- Patched driveway
- Cleaned floor drains

Yard Two

- Changed fuel filters
- Installed new switch in grinder
- Cleaned floor drains

Yard Four

- Changed pump filters and installed new pump handle

NESC

- Installed shelving and miscellaneous hardware and hose fittings
- Finished brine fill bar
- Installed brine tanks
- Installed power washers