

## WASHTENAW COUNTY ROAD COMMISSION

**TO:** Washtenaw County Board of Road Commissioners  
**FROM:** Roy D. Townsend, P.E.  
Managing Director  
**SUBJECT:** Staff Report – 4-9-18 to 4-22-18  
**DATE:** May 1, 2018

### TOWNSHIP REPORT

#### OPERATIONS REPORT

---

#### MAINTENANCE

Patching of paved roads took place throughout the County. In addition, the following specific maintenance activities were performed in individual townships.

#### ANN ARBOR TOWNSHIP

- Fallen Trees – Earhart Road, Goss Road, N Maple Road
- Limestone Patch – Earhart Road, Gleaner Hall Road, N Maple Road, W Joy Road, Warren Road: 75 tons
- Fallen Trees – Gleaner Hall Road

#### AUGUSTA TOWNSHIP

- Cleaned Culverts – E Willow Road
- Limestone Patch – Augusta Street, Bunton Road, Butler Road, Church Street, Gotts Court, Liss Road, Meridian Street, Potter Road, Torrey Road, Tuttle Hill Road: 170 tons

#### BRIDGEWATER TOWNSHIP

- Gravel Patch – Arkona Road, Burmeister Road, Hack Road, Lima Center Road, Neblo Road, Schellenberger Road: 46 tons
- Limestone Patch – Hoelzer Road, Lima Center Road, Neal Road, Schellenberger Road, Schwab Road: 60 tons

#### DEXTER TOWNSHIP

- Drainage and Backslopes – Island Lake Road
- Fallen Trees – Quigley Road
- Limestone Patch – McKinley Road, Noah Road, Quigley Road: 23 tons

#### FREEDOM TOWNSHIP

- Drainage and Backslopes – Waters Road
- Gravel Patch – Bethel Church Road, Eisman Road, Ellsworth Road: 10 tons
- Limestone Patch – S Parker Road, Weber Road: 14 tons
-

LIMA TOWNSHIP

- Drainage and Backslopes – Old US-12
- Limestone Patch – S Dancer Road: 9 tons

LODI TOWNSHIP

- Limestone Patch – Dell Road, Parker Road, Weber Road, S Zeeb Road: 85 tons

LYNDON TOWNSHIP

- Gravel Patch – Roe Road: 12 tons

MANCHESTER TOWNSHIP

- Drainage and Backslopes – English Road, Henzie Road
- Fallen Trees – Ely Road, Sharon Hollow Road, W Waters Road
- Gravel Patch – Wolff Road: 10 tons
- Limestone Patch – Burtless Road, Fahey Road, Hudson Road, Lemm Road: 36 tons
- Roadside – Herman Road

NORTHFIELD TOWNSHIP

- Culvert Replacement – E Northfield Church Road
- Drainage and Backslopes – Earhart Road, E Northfield Church Road, N Territorial Road, Seven Mile Road
- Limestone Patch – Earhart Road, E Joy Road, Five Mile Road, Kearney Road, Nollar Road, Service Drive, Spencer Road: 180 tons
- Repair Sinkhole – Hellner Road

PITTSFIELD TOWNSHIP

- Drainage and Backslopes – E Textile Road, Tuttle Hill road
- Fallen Trees – W Bemis Road, Fosdick Road, Oak Valley Drive, Merritt Road, Platt Road, Textile Road
- Limestone Patch – Stone School Road, W Textile Road, Warner Road: 42 tons

SALEM TOWNSHIP

- Boom Mow – Brookville Road, N Dixboro Road, Five Mile Road, Six Mile Road, Tower Road
- Drainage and Backslopes – Eight Mile Road
- Fallen Trees – E Joy Road, Five Mile Road, N Dixboro Road
- Limestone Patch – Brookville Road, E Joy Road, N Dixboro Road, Tower Road: 120 tons

SALINE TOWNSHIP

- Drainage and Backslopes – Case Road
- Fallen Trees – Abel Road, Arkona Road, Braun Road, Dell Road, Feldkamp Road, Hack Road, Johnson Road, Klager Road, Macon Road, Marion Road, Mohart Road, Roehm Road, Schill Road
- Limestone Patch – Dell Road: 45 tons

SCIO TOWNSHIP

- Limestone Patch – Tubbs Road: 15 tons

### SHARON TOWNSHIP

- Gravel Patch – Jacob Road, Meyers Road, Sharon Hollow Road, Sharon Valley Road, Sylvan Road, Washburne Road: 21 tons
- Limestone Patch – Kendall Road: 13 tons

### SUPERIOR TOWNSHIP

- Fallen Trees – Ford Road, Gale Road, Plymouth Road
- Limestone Patch – Berry Road, Gale Road, Gotfredson Road, N Prospect Street, Warren Road: 111 ton
- Limestone Patch Shoulders – N Prospect Street: 1 ton
- Roadside – Ford Road, Geddes Road

### SYLVAN TOWNSHIP

- Fallen Trees – Fahrner Road

### WEBSTER TOWNSHIP

- Gravel Patch – Valentine Road: 15 tons
- Limestone Patch – Daly Road, Strawberry Lake Road, Vaughn Road: 30 tons

### YORK TOWNSHIP

- Limestone Patch – W Begole Road, Judd Road, Mooreville Road, Petersburg Road, Warner Road: 105 tons

### YPSILANTI TOWNSHIP

- Berming – Rawsonville Road
- Boom Mow – Golfside Drive, N Hewitt Road, W Packard Road
- Cleaned Culverts – Tuttle Hill Road
- Fallen Trees – Burns Street, Campbell avenue, Edison Street, Elmhurst Street, S Harris Road, N Hewitt Road, Hillcrest Boulevard, Jay Avenue, Lakeview Avenue, Lester Avenue, Maulbetsch Street, McGregor Road, Midvale Street, Midway Street, N Clubview Drive, W Packard Road, Parkwood Avenue, Rawsonville Road, Service Drive, Share Avenue, Shirley Drive, Textile Road, Tuttle Hill Road, Verna Street
- Limestone Patch – Bemis Road, Huron Road, Huron River Drive, Textile Road, Tuttle Hill Road: 51 tons
- Limestone Patch Shoulders – Bridge Road, McCartney Avenue, McKean Road, Rawsonville Road, Textile Road, Tyler Road, Wiard Road: 54 tons

### WINTER MAINTENANCE

- Crews Responded – 3 times
- Total Salt Used – 827 tons
- Total Abrasives Used – 69 tons
- Total Brine Used – 280 gallons

### **NESC Updates**

Warranty work is ongoing as well as working with contractors for additional equipment installation. Electronic Security Systems, Inc. is completing our gate controls.

## **SHOP REPORT**

### **Shop Repairs**

- Tires Repaired – 7 tires
- New Tire Installation – 9 tires
- Vehicles Serviced – 4
- Vehicles Serviced by Suburban Chevrolet – 7
- Work Orders Completed – 41

### **Equipment Repair**

Note: Sent 9 Wester Stars to D&K for defroster repairs

- Truck 112 – Replaced radiator
- Truck 125 – Replaced front brakes and a caliper
- Truck 181 – Resealed the intake manifold, replaced air bag sensor and had seat recovered
- Truck 320 – Replaced batteries and alternator
- Truck 330 – Replaced air tanks and installed a different scraper
- Truck 359 – Repaired brine plumbing, heater motor, A/C, and changed tires
- Truck 381 – Replaced batteries and rear wiring harness, and cleaned salt out of frame
- Tractor 822 – Repaired throttle
- Mower 1022 – Repaired boom

## **BUILDING & GROUNDS REPORT**

### **Yard One**

- Salt sidewalks
- Lawn Cleanup
- Repair shop rapid unit
- Replace motor in parking garage rapid unit
- Repair lights
- Plumbing repair
- Recycle tires
- Paper and metal
- Janitorial
- Replace air hose reels in shop

### **Yard Two**

- Repair oil dispenser valve in parking garage
- Repair garage door

### **NESC**

- Installed curtain on vector dump shed
- Worked on brine system