

WASHTENAW COUNTY ROAD COMMISSION

TO: Washtenaw County Board of Road Commissioners

FROM: Sheryl Soderholm Siddall, P.E.
Managing Director

SUBJECT: Staff Report – 7-30-18 to 8-12-18

DATE: August 21, 2018

TOWNSHIP REPORT

OPERATIONS REPORT

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Fallen Tree – Riverside Drive

AUGUSTA TOWNSHIP

- Fallen Tree – Bolla Road
- Limestone Patch – Liss Road: 40 tons
- Local Road Dust Control
- Primary Road Dust Control
- Tuttle Hill Road Limestone Resurfacing Project Final Grade

BRIDGEWATER TOWNSHIP

- Limestone Patch Shoulders – Austin Road: 34 tons
- Local Road Dust Control
- Primary Road Dust Control

DEXTER TOWNSHIP

- Gravel Patch Shoulders – Dexter-Pinckney Road, N Territorial Road: 4 tons

FREEDOM TOWNSHIP

- Fallen Tree – Pleasant Lake Road
- Limestone Patch Shoulders – Pleasant Lake Road: 29 tons
- Primary Road Dust Control

LIMA TOWNSHIP

- Cut Trees – Luick Drive
- Fallen Tree – Trinkle Road
- Local Road Dust Control

LODI TOWNSHIP

- Culvert Replacement – Bethel Church Road
- HMA Overlay – Weber Road
- HMA Resurfacing – Ann Arbor-Saline Road
- HMA Wedging – Golfview Court
- Bethel Church Road Limestone Resurfacing – 5,500 tons
- Primary Road Dust Control

LYNDON TOWNSHIP

- Drainage and Backslopes – Beeman Road
- Fallen Tree – Boyce Road, Joslin Lake Road, Loveland Road, Waterloo Road
- Gravel Patch Shoulders – Hadley Road, N Territorial Road, Stofer Road, Waterloo Road: 10 tons
- Limestone Patch – Cassidy Road: 6 tons
- Seed and Straw Project – Beeman Road

MANCHESTER TOWNSHIP

- Culvert Replacement – Van Tuyle Road
- Fallen Trees – English Road, Sharon Hollow Road
- Gravel Patch – Bowens Road, English Road, Grossman Road, Mulvaney Road, Wellwood Road: 105 tons
- Limestone Patch Shoulders – Austin Road: 11 tons
- Local Road Dust Control
- Primary Road Dust Control
- Seed and Straw – Van Tuyle Road

NORTHFIELD TOWNSHIP

- Culvert Replacement – Five Mile Road, Kearney Road
- Drainage and Backslopes – Five Mile Road, Six Mile Road
- Fallen Tree – Six Mile Road
- Roadside Debris – E Shore Drive, Seven Mile Road

PITTSFIELD TOWNSHIP

- Cleaned Catch Basins – Hidden Creek Drive, Primrose Lane
- Cleared Drains – W Ellsworth Road
- Drainage and Backslopes – Carpenter Road, Crystal Drive, Ellsworth Road, Golfside Drive, Lohr Road, Packard Street
- Fallen Trees – Amber Way, E Bemis Road, Campbell Road, Carlton Street, Cottonwood Drive, Crane Road, Merritt Road, Robison Lane, Sauk Trail, Stone School Road, Thomas Road
- HMA Resurfacing – Crane Road
- Repaired Drains – Maple Drive, Oakdale Drive
- Repair Washout – Ann Arbor Saline Road, S Maple Road
- Roadside Debris – Carpenter Road

SALEM TOWNSHIP

- Berming – Seven Mile Road
- Cleaned Pipes – Brookville Road, Dixboro Road, Tower Road
- Culvert Replacement – Currie Road, N Dixboro Road
- Drainage and Backslopes – N Dixboro Road, McFadden Street
- Fallen Tree – Curtis Road
- HMA Resurfacing – Currie Road
- Limestone Patch – Five Mile Road, N Dixboro Road, Six Mile Road: 57 tons
- Local Road Dust Control

SALINE TOWNSHIP

- Brush Removal – Grass Road
- Fallen Tree – Jordan Road
- Limestone Patch – Parker Road: 17 tons
- Limestone Patch Shoulders – Arkona Road, Austin Road, Jordan Road, Macon Road, Parker Road: 119 tons
- Primary Road Dust Control
- Grass Road Limestone Resurfacing Project – 661 tons
- Maple Road Limestone Resurfacing Project – 101 tons
- Mohart Road Limestone Resurfacing Project – 1,993 tons
- Roehm Road Limestone Resurfacing Project – 1,998 tons

SCIO TOWNSHIP

- Local Road Dust Control

SUPERIOR TOWNSHIP

- Fallen Tree – Cherry Hill Road
- Limestone Patch – Gotfredson Road, N Harris Road, Vreeland Road: 48 tons
- Local Road Dust Control

SYLVAN TOWNSHIP

- Gravel Patch – Hayes Road, Liebeck Road: 24 tons
- Gravel Patch Shoulders – Cavanaugh Lake Road, Old US-12: 4 tons
- Local Road Dust Control
- Primary Road Dust Control
- Notten Road Gravel Resurfacing – 540 tons
- Township Wide Limestone Resurfacing – Heim Road, Kalmbach Road, Winters Road: 2,039 tons

WEBSTER TOWNSHIP

- Cut Trees – Valentine Road

YORK TOWNSHIP

- Fallen Trees – S Maple Road, Sanford Road
- Limestone Patch – Judd Road, Sheryl Drive – 10 tons
- Local Road Dust Control

YPSILANTI TOWNSHIP

- Cleaned Catch Basins – Dorothy Street, Harry Street, Phyllis Street
- Drainage and Backslopes – Grove Road, Lakeway Street
- Drain and Curb Repair – Grove Road
- Ditching – Textile Road
- Fallen Trees – Aspen Way, E Bemis Road, Berkley Street, Boyne Drive, Ellis Road, W Hereford Court, Jonquil Lane, Martz Road, Red Bird Drive, Stony Creek Road, Textile Road, Wharton Street, Whittaker Road
- Grind Stumps – Chevrolet Street, Clark Service Drive, Harmon Street, Juneau Road, Nash Avenue, Rue Willette Boulevard, Studebaker Avenue, Tyler Road
- Repaired Drain – Grove Road
- Repaired Washout – Textile Road
- Roadside Debris – Martz Road, Merritt Road, Whittaker Road
- Saw Cut Curb – Grove Road
- Sweep and Flush – Bunton Road, Martz Road, Merritt Road, Stony Creek Road, Textile Road, Tuttle Hill Road

NESC Updates

Warranty work is ongoing as well as additional equipment installation. The security initiatives for NESC, SESC and the Main Yard gate controls continue.

SHOP REPORT**Shop Repairs**

- Tires Repaired – 10 tires
- New Tire Installation – 7 tires
- Vehicles Serviced – 5
- Vehicles Serviced by Suburban Chevrolet – 1
- Work Orders Completed – 23

Equipment Repair**Note:**

- Pump 1014 – Resealed brine pump
- Trailer 1199 – Replaced outlet pipe
- Truck 366 – Brine truck conversion, calibrated and put into service
- Truck 375 – Replaced an injector and installed rear hitch
- Truck 383 – Repaired wiring for DEF and A/C systems
- Truck 390 – Repaired bent flight chain

BUILDING & GROUNDS REPORT

Yard One

- Painted around fuel island, bollards, office hand rails and doors
- Lawn work
- Cleaned drains in parking garage
- Repaired floor in parking garage
- Recycling and janitorial

Yard Two

- Painted fuel island, bollards and doors
- Lawn work
- Plumbing repairs

Yard Three

- Repaired shingles on salt barn
- Repaired A/C
- Installed conduit for flag pole
- Replaced broken window

Yard Four

- Lawn work
- Fuel system repairs

NESC

- Installed hoses and rail trolley system on pressure washer
- Monitored HVAC

Brine Well

- Yard work
- Tighten packings
- Monitored well