

WASHTENAW COUNTY ROAD COMMISSION

TO: Washtenaw County Board of County Road Commissioners
FROM: Sheryl Soderholm Siddall, P.E.
Managing Director
SUBJECT: Staff Report – 8-13-18 to 8-26-18
DATE: September 4, 2018

TOWNSHIP REPORT

OPERATIONS REPORT

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Local Road Dust Control

AUGUSTA TOWNSHIP

- Cut Trees – Butler Road
- Ditching – Butler Road
- Drainage and Backslopes – Butler Road
- Fallen Tree – Willis Road
- Local Road Dust Control

BRIDGEWATER TOWNSHIP

- Drainage and Backslopes – Allen Road, Sheridan Road, Willow Road
- Fallen Tree – Logan Road, Wilbur Road
- Gravel Patch – Burmeister Road: 11 tons
- Local Road Dust Control

DEXTER TOWNSHIP

- Boom Mow – N Territorial Road, Stofer Road
- Limestone Patch – Riker Road: 16 tons
- Local Road Dust Control

LIMA TOWNSHIP

- Local Road Dust Control
- Township-wide Limestone Resurfacing – Freer Road, Guenther Road, Lima Center Road, Steinbach Road: 3,149 tons

LODI TOWNSHIP

- Limestone Patch – Ellsworth Road, Waters Road: 12 tons
- Local Road Dust Control
- Primary Road Dust Control
- Township-wide Limestone Resurfacing Project – Bethel Church Road, Weber Road: 1,758 tons

LYNDON TOWNSHIP

- Boom Mow – N Territorial Road
- Cleaned Drains – Guinan Drive
- Limestone Patch – Guinan Drive: 5 tons
- Primary Road Dust Control

MANCHESTER TOWNSHIP

- Drainage and Backslopes – Bowens Road, Henzie Road, Kirk Road, Lemm Road, Schleweis Road, Tracey Road
- Fallen Trees – Herman Road
- Limestone Patch Shoulders – Watkins Road: 1 ton
- Local Road Dust Control

NORTHFIELD TOWNSHIP

- Chipseal – Seven Mile Road
- Limestone Patch – Six Mile Road: 28 tons

PITTSFIELD TOWNSHIP

- Fallen Trees – Morgan Road, Moon Road, State Road
- Roadside Debris – State Road

SALEM TOWNSHIP

- Berming – Joy Road
- Chipseal – Pontiac Trail, Seven Mile Road
- Culvert Replacement – Currie Road
- Fallen Tree – N Territorial Road

SALINE TOWNSHIP

- Limestone Patch – Mooreville Road: 20 tons
- Limestone Patch Shoulders – Austin Road: 17 tons

SHARON TOWNSHIP

- Gravel Patch – Sharon Hollow Road: 19 tons
- Sylvan Road Gravel Resurfacing Project – 2,673 tons

SCIO TOWNSHIP

- Local Road Dust Control

SUPERIOR TOWNSHIP

- Culvert Replacement – Warren Road
- Drainage and Backslopes – Warren Road
- Fallen Tree – Superior Road
- Limestone Patch – Warren Road: 18 tons
- Local Road Dust Control
- Roadside Debris – Cherry Hill Road, Geddes Road

SYLVAN TOWNSHIP

- Boom Mow – Old US-12 Road
- Fallen Trees – Hayes Road

WEBSTER TOWNSHIP

- Cut Trees – Valentine Road
- Limestone Patch – Barker Road, Scully Road: 1 tons

YORK TOWNSHIP

- Fallen Trees – N Sanford Road
- Limestone Patch – Mooreville Road: 20 tons

YPSILANTI TOWNSHIP

- Brush Removal – Canyon Drive, Cascade Lane, Congress Street, Hazel Court, Hewitt Road, Highland Court
- Cleared Drains – Colony Way, Cross Street, Hewitt Road, Holmes Road
- Concrete Curb and Gutter Removal and Replacement – S Ivanhoe Avenue, James Avenue, S Miami Avenue, S Mohawk Avenue
- Cut Trees – Hearthside Drive, Stony Creek Road
- Fallen Trees – Textile Road
- Limestone Patch – Bemis Road, Ellis Road, Morgan Road: 90 tons
- Limestone Patch Shoulders – Rawsonville Road, Snow Avenue, Textile Road: 19 tons
- Repaired Drain – Ivanhoe Avenue, Platt Road
- Repaired Shoulder – Morgan Road
- Roadside Debris – Oak Valley Drive, Parkwood Avenue, Whittaker Road

NESC Updates

Warranty work and additional equipment installation by contractors is on-going. The architect made a visit and updated their punch list for items not yet completed. Work on the NESC, SESC, and Main Yard gate controls continued.

SHOP REPORT

Shop Repairs

- Tires Repaired – 5 tires
- New Tire Installation – N/A
- Vehicles Serviced – 7
- Vehicles Serviced by Suburban Chevrolet – 4
- Work Orders Completed – 34

Equipment Repair

Note: Performed several electrical, hydraulic and A/C repairs

- Grader 463 – Adjusted valves
- Grader 471 – Installed rear fenders
- Truck 325 – Replaced the main hydraulic hose
- Truck 328 – Replaced the batteries
- Truck 378 – Replaced the DEF pump air regulator

BUILDING & GROUNDS REPORT

Yard One

- Janitorial
- Recycling
- Lawn work
- Plumbing repairs

Yard Two

- Lawn work
- Fuel system repairs

Yard Three

- Flag pole light wiring
- Lawn work

Yard Four

- Lawn work
- Swap out brine pump assembly for warranty
- Brine plumbing repairs

NESC

- Installed remote wiring for power washers
- Lawn work

Brine Well

- Lawn work
- Monitored well