# WASHTENAW COMMISSION

### **WASHTENAW COUNTY ROAD COMMISSION**

# TOWNSHIP/STAFF REPORT - November 6, 2018

# For the period of November 12, 2018 thru November 25, 2018

# TOWNSHIP REPORT

#### **OPERATIONS REPORT**

#### **MAINTENANCE**

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

#### ANN ARBOR TOWNSHIP

Limestone Patch – Earhart Road: 34 tons

#### AUGUSTA TOWNSHIP

- Canopy Clearing Butler Road
- Drainage and Backslopes Willow Road
- ➤ McCrone Road Limestone Resurfacing Project 5,789 tons

#### **BRIDGEWATER TOWNSHIP**

McCollum Road Limestone Resurfacing Project – 5,504 tons

#### **DEXTER TOWNSHIP**

- Drainage and Backslopes Dexter-Pinckney Road
- > Gravel Patch Dexter Townhall Road, Toma Road: 31 tons
- Limestone Patch Brand Road, Island Lake Road, Madden Road, Toma Road, Winston Road: 27 tons

#### FREEDOM TOWNSHIP

Limestone Patch – Parker Road: 20 tons

### LIMA TOWNSHIP

- Boom Mow Wylie Road, Scio Church Road
- ➤ Border-to-Border City of Chelsea to Lima Center Road Pathway Tree Removal
- Ditching N Lima Center Road
- Drainage and Backslopes Steinbach Road
- Limestone Patch Fletcher Road, Gross Road, S Lima Center Road, N Steinbach Road: 32 tons

#### LODI TOWNSHIP

- ➤ Fallen Tree Brian Glenn Drive
- Limestone Patch Waters Road: 15 tons
- ➤ Limestone Patch Shoulders Ann Arbor-Saline Road: 2 tons

## LYNDON TOWNSHIP

- Gravel Patch Bowdish Road, Joslin Lake Road: 9 tons
- ➤ Limestone Patch Roepke Road: 30 tons

#### MANCHESTER TOWNSHIP

Drainage and Backslopes – Grossman Road, Mull Road

#### NORTHFIELD TOWNSHIP

- Limestone Patch Earhart Road, Eight Mile Road, Five Mile Road, Jennings Road, Joy Road, Nollar Road, Northfield Church Road, Rushton Road: 255 tons
- ➤ Limestone Patch Shoulders Six Mile Road, N Territorial Road: 15 tons

#### PITTSFIELD TOWNSHIP

- Cut Brush Platt Road
- Drainage and Backslopes Rosefield Drive
- Fallen Trees Campbell Road
- Roadside Debris S State Road
- Limestone Patch Morgan Road, Stone School Road: 63 tons

#### SALEM TOWNSHIP

- Cut Trees Brookville Road
- Fallen Trees Curtis Road, Seven Mile Road
- Limestone Patch Dixboro Road, Five Mile Road, Napier Road: 85 tons

### SALINE TOWNSHIP

- Berming Case Road
- Culvert Replacement Case Road
- Ditching Macon Road
- Limestone Patch Arkona Road, Mooreville Road: 120 tons

#### SCIO TOWNSHIP

- Boom Mow Liberty Road
- Limestone Patch Shoulders Miller Road, Parker Road, Zeeb Road: 4 tons

#### SHARON TOWNSHIP

- Gravel Patch Below Road: 6 tons
- Limestone Patch Below Road, Bethel Church Road: 16 tons

#### SUPERIOR TOWNSHIP

- Brush Removal Leforge Road, N Prospect Road
- ➤ Limestone Patch Albert Drive, Gotfredson Road, Hickman Road, Leforge Road, Stommel Road, Vreeland Road: 19 tons
- Local Road Dust Control

#### WEBSTER TOWNSHIP

Limestone Patch Shoulders – Mast Road: 2 tons

#### YORK TOWNSHIP

- Ditching Maple Road, Willow Road
- ➤ HMA Resurfacing Moon Road
- ➤ Limestone Patch Mooreville Road, Petersburg Road: 70 tons
- ➤ Shoulder Placement Platt Road

#### YPSILANTI TOWNSHIP

- ➤ ADA Ramp Installation Gates Avenue, Tyler Road, Parkwood Avenue, Hawthorne Avenue
- Brush Removal Allen Avenue, Jerome Avenue
- Limestone Patch Ellis Road, Morgan Road: 42 tons
- ➤ HMA Resurfacing The Pines Subdivision
- > Roadside Debris Coolidge Road, Martz Road, Merritt Road, Rawsonville Road

## **WINTER MAINTENANCE**

- Crews Responded 6 times
- ➤ Total Salt Used 1.737 tons
- ➤ Total Abrasives Used 55 tons
- ➤ Total Brine Used 2,820 gallons

## **NESC REPORT**

Warranty work and additional equipment installation by contractors is on-going.

## **SHOP REPORT**

## **Shop Repairs**

- ➤ Tires Repaired 4 tires
- ➤ New Tire Installation 20
- ➤ Vehicles Serviced 1
- Vehicles Serviced by Suburban Chevrolet 10
- ➤ Work Orders Completed 38

# **Equipment Repair**

Note: Performed several hydraulic repairs

- ➤ Grader 464 Replaced the console wiring harness
- ➤ Grader 476 Replaced the turbo, bent steps and broken lights
- ➤ Roller 1093 Replaced the park brake shoes and repaired the shifter
- Scraper 358 Refurbished and installed on truck 374
- > Truck 370 Replaced the starter
- ➤ Truck 381 Replaced an injector, rear air bag and repaired the flight chain

## **BUILDING & GROUNDS REPORT**

# Yard One

- ➤ Painted walls, installed new ceiling tiles, installed new ceiling fan, and stripped and waxed floor in Foreman's office
- Winter maintenance
- Cleaned parking garage floors
- Installed new stove for office lunchroom
- Rodent control

## Yard Two

- ➤ Repaired lights
- > Repairs to rapid unit
- Repaired bathroom sink

## Yard Four

Replaced filter in drinking fountain

# Yard Six

- Installed signage
- Repaired DEF dispenser
- Repairs to brine system