

WASHTENAW COUNTY ROAD COMMISSION

TO: Washtenaw County Board of Road Commissioners
FROM: Roy D. Townsend, P.E.
Managing Director
SUBJECT: Staff Report – 11-27-17 to 12-10-17
DATE: December 19, 2017

TOWNSHIP REPORT

OPERATIONS REPORT

A. Maintenance

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Limestone Patch Shoulder – N Dixboro Road
- Repair Guardrail – Maple Road
- Roadside Trash Removal – E Huron River Drive

AUGUSTA TOWNSHIP

- Culvert Replacement – Talladay Road, Tuttle Hill Road
- Drainage and Backslopes – Talladay Road, Tuttle Hill Road
- Limestone Patch – Butler Road, Macey Road, Rosbolt Road, Talladay Road, Tuttle Hill Road: 220 tons

BRIDGEWATER TOWNSHIP

- Boom Mow – Schneider Road
- Drainage and Backslope – McCollum Road
- Fallen Trees – Allen Road
- Gravel Patch – Bowens Road, Eisman Road: 13 tons
- Limestone Patch – Austin Road, Eisman Road, Ernst Road, Hogan Road, Lima Center Road, Logan Road, Wilbur Road: 101 tons
- Limestone Patch Shoulders – W Austin Road: 20 tons
- Roadside – Sheridan Road

DEXTER TOWNSHIP

- Limestone Patch – Madden Road: 10 tons
- Sweeping and Flushing – Dancer Road

FREEDOM TOWNSHIP

- Boom Mow – Schneider Road
- Gravel Patch – Saline Waterworks Road: 8 tons
- Roadside – Pleasant Lake Road

LODI TOWNSHIP

- Boom Mow – Pleasant Lake Road
- Limestone Patch – Gensley Road, Grass Road, Noble Road, Tessmer Road, Waters Road, Weber Road: 30 tons
- Limestone Patch Shoulders – Ann Arbor-Saline Road, Pleasant Lake Road, Wagner Road: 15 tons

LYNDON TOWNSHIP

- Culvert Replacement – Guinan Drive
- Drainage and Backslopes – Guinan Drive
- Gravel Patch – Bartell Road, Goodband Road, Osius Road: 13 tons

MANCHESTER TOWNSHIP

- Boom Mow – Sharon Hollow Road
- Gravel Patch – Bowens Road, Burtless Road, Henzie Road, Lemm Road, Noggles Road: 56 tons
- Limestone Patch – Grossman Road, Lehman Road, Sylvan Road, Wingate Road: 13 tons
- Limestone Patch Shoulders – E Shore Drive: 14 tons
- Roadside – Henzie Road

NORTHFIELD TOWNSHIP

- Berming – Earhart Road, N Maple Road
- Culvert Replacement – Earhart Road, N Maple Road
- Cut Trees – Sutton Road
- Drainage and Backslopes – Earhart Road, Five Mile Road, Rushton Road
- Fallen Trees – Sutton Road
- Limestone Patch – Hellner Road, E Joy Road, N Maple Road, Six Mile Road, Spencer Road: 61 tons

PITTSFIELD TOWNSHIP

- Boom Mow – Maple Road, Morgan Road, Textile Road, Thomas Road
- Checked Drains – Ann Arbor-Saline Road, Lohr Road, Oak Valley Drive, W Ellsworth Road, W Lohr Road, W Waters Road
- Cut Trees – Aspen Ridge Drive
- Fallen Trees – Aspen Ridge Drive
- Grind Stumps – Golfside Drive
- Limestone Patch – Marton Road, Morgan Road, Stone School Road, W Textile Road, Thomas Road: 126 tons
- Limestone Patch Shoulders – State Road: 30 tons
- Roadside – E Bemis Road, Ellsworth Road, Merritt Road, Munger Road, Wildwood Drive

SALEM TOWNSHIP

- Culvert Repair – Dixboro Road
- Drainage and Backslopes – Brookville Road
- Limestone Patch – Chubb Road, Dixboro Road, Joy Road, Six Mile Road: 89 tons
- Roadside – N Dixboro Road

SALINE TOWNSHIP

- Boom Mow – Abel Road, Arkona Road, Avedon Lane, Baron Way, Berger Drive, Hack Road, Judd Road, Lindsley Road, Londonderry Drive, Sizemore Drive, Stony Creek Road
- Drainage and Backslopes – Arkona Road
- Fallen Trees – Austin Road
- Limestone Patch – Arkona Road, Case Road, Dell Road, Lindsley Road, Willow Road: 100 tons

SCIO TOWNSHIP

- Boom Mow – Knight Road
- Drainage and Backslopes – E Pine View Drive
- Gravel Patch – Park Road, Pheasant Drive: 15 tons
- Limestone Patch – Cottontail Lane, Huron River Drive, Miller Road, Parkridge Drive, Robinwood Drive, Wagner Road: 15 tons
- Limestone Patch Shoulders – Coventry Square Drive, Deerfield Place, Metty Drive, Pheasant Drive, Scio Church Road: 33 tons

SHARON TOWNSHIP

- Boom Mow – Sharon Hollow Road, Sharon Valley Road
- Cut Trees – Lehman Road
- Drainage and Backslopes – Sharon Hollow Road
- Gravel Patch – Easudes Road, Sharon Hollow Road: 23 tons

SUPERIOR TOWNSHIP

- Cleaned Pipes – Cherry Hill Road
- Limestone Patch – Frains Lake Road, Gotfredson Road, Warren Road: 42 tons
- Repair Washout – Gotfredson Road
- Roadside – Superior Road

SYLVAN TOWNSHIP

- Gravel Patch – Loveland Road: 8 tons

WEBSTER TOWNSHIP

- Limestone Patch – McClatchey Road, Merkel Road, Pellett Drive, Hamburg Road, Walsh Road: 15 tons
- Limestone Patch Shoulders – Mast Road: 5 tons

YORK TOWNSHIP

- Cleaned Pipes – Crane Road, Jewell Road
- Drainage and Backslopes – Arkona Road, Hack Road, Moon Road
- Grind Stumps – Jewell Road
- Limestone Patch – Crane Road, Judd Road, Warner Road: 36 tons

YPSILANTI TOWNSHIP

- Boom Mow – Merritt Rod, Munger Road
- Checked Drains – E Cross Street, E Forest Avenue, Grove Road, N Harris Road, Rawsonville Road, S Harris Road
- Cut Trees – E Bemis Road, Chevrolet Street, Tyler Road
- Drainage and Backslopes – Bunton Road, Cary Drive, Martz Road, McKean Road, Oakland Hills Drive
- Fallen Trees – E Forest Avenue, Tyler Road
- Grind Stumps – Burns Street, Calder Street, Chevrolet Street, Desoto Avenue, Eileen Street, Edison Street, Huntington Drive, Onandago Street, E Raintree Court, Raintree Drive, Zephyr Street
- Limestone Patch Shoulders – E Clark Road, E Forest Avenue, Merritt Road, S Huron River Drive, Stony Creek Road, Whittaker Road, Merritt Road, Midway Street, Ridge Road: 54 tons
- Repaired Drain – Oakland Hills Drive
- Roadside – E Bemis Road, Calder Street, Commonwealth Avenue, Crestwood Avenue, Desoto Avenue, Tuttle Hill Road

WINTER MAINTENANCE

- Crews Responded – 3 times
- Total Salt Used – 1,454 tons
- Total Abrasives Used – 44 tons
- Total Brine Used – 2,949 gallons

NORTHEAST SERVICE CENTER UPDATE

The exterior and interior siding work is complete. The fire protection equipment continues to be installed. The interior installation of electrical and mechanical work continues. Interior painting of the walls continues as areas are available. The HMA for the season has been completed. The entrance along N. Territorial has been completed and 95% of the base coarse is completed and 80% of the wearing coarse has been placed. The remaining utilities are complete. The heating and cooling has been turned on and balancing of the system is currently ongoing. The finishes of paint, tile and fixtures are being installed.

SHOP REPORT

Shop Repairs

- Tires Repaired – 3 tires
- New Tire Installation – 57
- Vehicles Serviced – 9
- Vehicles Serviced by Suburban Chevrolet – 7
- Work Orders Completed – 23

Equipment Repair

Note: Repaired multiple salter electrical issues

- Truck 320 – A new dump box was installed
- Truck 333 – A new dump box was installed
- Truck 351 – Replaced the transmission radiator, water pump, exhaust pipe and an air tank
- Truck 354 – Installed the dump box and subframe
- Truck 366 – Installed the dump box and subframe
- Truck 373 – Replaced the heater blend door

BUILDING & GROUNDS REPORT

Yard One

- Installed new panels on fuel canopy
- Installed new belts on shop rapid unit
- Painted in shop break room
- Repaired drywall and paint in office bathroom
- Relocated Wi-Fi in assembly Room
- Plumbing repairs
- Repaired and Cleaned gutters
- Yard clean up
- Janitorial
- Recycling

Yard Two

- Repaired garage doors
- Repaired furnace

Yard Four

- Repaired brine pump

NORTHEAST SERVICE CENTER

- Worked on overhead brine loading bar
- Supplies for janitorial

MEETINGS ATTENDED:

- 11/28 J. Harmon attended the regular meeting of the Washtenaw County Homeland Security Task Force
- 11/29 Staff participated in a Ford Lake Dam Emergency Action Plan telephone exercise alarm test
- 12/5 J. Harmon and S. Siddall met with York Township officials to discuss potential road improvements and funding opportunities
- 12/6 J. Harmon attended a Superintendents Association of Michigan Board of Directors meeting held at the Clinton County Road Commission