

WASHTENAW COUNTY ROAD COMMISSION

TO: Washtenaw County Board of Road Commissioners
FROM: Roy D. Townsend, P.E.
Managing Director
SUBJECT: Staff Report – 12-11-17 to 12-24-17
DATE: January 3, 2018

TOWNSHIP REPORT

OPERATIONS REPORT

MAINTENANCE

The following maintenance activities were performed in individual townships:

AUGUSTA TOWNSHIP

- Drainage and Backslopes – Hitchingham Road

DEXTER TOWNSHIP

- Brush Removal – Dexter Pinckney Road

FREEDOM TOWNSHIP

- Boom Mow – Fletcher Road, Pleasant Lake Road

LODI TOWNSHIP

- Drainage and Backslopes – Diuble Road

NORTHFIELD TOWNSHIP

- Canopy Cutting – Sutton Road
- Cut Trees – Sutton Road

PITTSFIELD TOWNSHIP

- Closed Culvert – Bemis Road
- Cut Asphalt – Bemis Road
- Roadside – Carpenter Road
- Structure Maintenance – Bemis Road

SALEM TOWNSHIP

- Fallen Trees – Seven Mile Road

SALINE TOWNSHIP

- Boom Mow – Arkona Road, Macon Road

SCIO TOWNSHIP

- Bump Grinding – Baker Road

SHARON TOWNSHIP

- Boom Mow – Pleasant Lake Road

SYLVAN TOWNSHIP

- Brush Removal – Ivey Road, Sibley Road

YORK TOWNSHIP

- Drainage and Backslopes – Mooreville Road

YPSILANTI TOWNSHIP

- Boom Mow – Ellis Road, Merritt Road
- Limestone Patch – E Bemis Road, Munger Road: 36 tons

WINTER MAINTENANCE

- Crews Responded – 11 times
- Total Salt Used – 6,507 tons
- Total Abrasives Used – 250 tons
- Total Brine Used – 14,065 gallons

NESC Updates

The fire protection equipment continues to be installed. Electrical and mechanical inspections are being completed. Interior paint touch-ups of the walls continue. Testing and inspections of the water system are on-going and the driveway gate has been installed.

SHOP REPORT

Shop Repairs

- Tires Repaired – 4 tires
- New Tire Installation – 10
- Vehicles Serviced – 2
- Vehicles Serviced by Suburban Chevrolet – 3
- Work Orders Completed – 19

Equipment Repair

Note: Repaired multiple salter electrical issues and hydraulic leaks.

- Truck 326 – Replaced the worn scraper with a good used one
- Truck 358 – Replaced the turn signal switch
- Mower 889 – Welded and reinforced the boom support

BUILDING & GROUNDS REPORT

Yard One

- Replaced brine transfer pump
- Made brine hoses
- Winter maintenance on sidewalk and parking lot
- Electrical repairs
- Plumbing repairs
- Janitorial
- Recycling

Yard Three

- Pump oil separators

Yard Four

- Replaced brine nozzle
- Cleaned drains
- Pump oil separator

NESC

- Work on brine system
- Purchased facilities supplies