

WASHTENAW COUNTY ROAD COMMISSION

TO: Washtenaw County Board of Road Commissioners
FROM: Sheryl Soderholm Siddall, P.E.
Managing Director
SUBJECT: Staff Report – 7-9-18 to 7-29-18
DATE: August 7, 2018

TOWNSHIP REPORT

OPERATIONS REPORT

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Fallen Tree – N Dixboro Road

AUGUSTA TOWNSHIP

- Fallen Trees – McKean Road, Talladay Road, Willis Road
- Gotts Court Limestone Resurfacing – 359 tons
- Shoulder Maintenance – Willis Road
- Tuttle Hill Road Limestone Resurfacing – 6,823 tons

BRIDGEWATER TOWNSHIP

- Fallen Trees – Allen Road
- Limestone Patch – McCollum Road: 61 tons
- Limestone Patch Shoulders – W Austin Road
- Roadside Debris – Sheridan Road

DEXTER TOWNSHIP

- Berming – Dexter-Pinckney Road
- Drainage and Backslopes – N Territorial Road
- Limestone Patch – Wylie Road: 19 tons
- Local Road Dust Control
- Primary Road Dust Control
- Shape and Brine Limestone Resurfacing Project – Lima Center Road

FREEDOM TOWNSHIP

- Gravel Patch – Bemis Road, Peckins Road, Wylie Road: 34 tons
- Local Road Dust Control
- Primary Road Dust Control

LIMA TOWNSHIP

- Brush Removal – Scio Church Road
- Gravel Patch – Dexter-Chelsea Road: 22 tons
- Limestone Patch – Lima Center Road: 7 tons
- Local Road Dust Control
- Shape and Brine Limestone Resurfacing Project – Lima Center Road

LODI TOWNSHIP

- Cut Trees – Bethel Church Road
- Gravel Patch – Zeeb Road: 6 tons
- Limestone Patch – Zeeb Road: 26 tons
- Primary Road Dust Control

LYNDON TOWNSHIP

- Culvert Replacement – Beeman Road, Roe Road
- Drainage and Backslopes – Beeman Road
- Fallen Tree – Cassidy Road
- Gravel Patch – Beeman Road, Boyce Road, Cassidy Road, Joslin Lake Road, Island Lake Road, Leeke Road, Waterloo Road: 53 tons
- Local Road Dust Control
- Primary Road Dust Control
- Shape and Brine Limestone Resurfacing Project – Roepke Road

MANCHESTER TOWNSHIP

- Culvert Replacement – Henzie Road, Van Tuyle Road
- Fallen Trees – Schleweis Road
- Gravel Patch – Grossman Road, Sandborn Road, Van Tuyle Road: 38 tons
- Limestone Patch – Henzie Road, Herman Road, Watkins Road: 20 tons
- Limestone Patch Shoulders – Herman Road: 2 tons
- Primary Road Dust Control
- Repair Washout – Sharon Hollow Road

NORTHFIELD TOWNSHIP

- Cut Trees – Brookville Road
- Local Road Dust Control

PITTSFIELD TOWNSHIP

- Berming – Crane Road
- Brush Removal – Crane Road
- Culvert Repair – Lohr Lake Drive
- Fallen Tree – Amber Way, Carlton Street, Crane Road, Lohr Road, Merritt Road, Rothbury Court, Sauk Trail, Stone School Road
- HMA Resurfacing – Crane Road
- Local Road Dust Control
- Repair Drain – Barry Knoll Drive, Briar Ridge Drive
- Roadside Debris – Mott Road, Crane Road
- Seed and Mulch – Barry Knoll Drive, Briar Ridge Drive
- Sweeping – Cayman Boulevard, Textile Road

SALEM TOWNSHIP

- Culvert Replacement – Five Mile Road
- Cut Trees – Brookville Road
- Drainage and Backslopes – Brookville Road, Dixboro Road, Tower Road
- Fallen Trees – Napier Road
- HMA Resurfacing – Currie Road

SALINE TOWNSHIP

- Berming – Grass Road, Mohart Road, S Maple Road, Roehm Road
- Brush Removal – Grass Road, Roehm Road
- Local Road Dust Control
- Primary Road Dust Control
- Maple Road Limestone Resurfacing – 2,000 tons

SALINE TOWNSHIP

- Local Road Dust Control

SHARON TOWNSHIP

- Fallen Trees – Pleasant Lake Road, Walker Road
- Gravel Patch – Parr Road, Sharon Hollow Road, Sharon Valley Road: 65 tons
- Limestone Patch Shoulders – Grass Lake Road: 4 tons
- Local Road Dust Control
- Primary Road Dust Control

SUPERIOR TOWNSHIP

- Fallen Trees – Stommel Road, Warren Road
- HMA Resurfacing – Wiard Road
- Limestone Patch – Cherry Hill Road, Gotfredson Road: 47 tons
- Seed and Mulch – Buckingham Drive

SYLVAN TOWNSHIP

- Berming – Old US-12
- Brush Removal – Cavanaugh Lake Road, Ivey Road, Notten Road, Old US-12, Sibley Road
- Culvert Replacement – Notten Road
- Fallen Tree – Sylvan Road
- Gravel Patch – Kilmer Road, Loveland Road: 12 tons

WEBSTER TOWNSHIP

- Gravel Patch – Farrell Road, Huron River Drive, Jennings Road, Northfield Church Road, Scully Road: 15 tons
- Limestone Patch – Base Lake Drive, Farrell Road, Huron River Drive, Jennings Road, Northfield Church Road, Scully Road: 25 tons
- Local Road Dust Control
- Merrill Road Limestone Resurfacing Project – 3,400 tons
- Valentine Road Limestone Resurfacing Project – 2,229 tons
- Webster Church Road Limestone Resurfacing Project – 5,832 tons

YORK TOWNSHIP

- Canopy Cutting – Bishop Road, Sanford Road
- Fallen Tree – Crane Road, Warner Road
- Limestone Patch – Hartman Road, Jewell Road, Judd Road, Milkey Road, Moon Road, S Maple Road, Samer Road, Petersburg Road: 60 tons
- Local Road Dust Control
- Primary Road Dust Control

YPSILANTI TOWNSHIP

- Brush Removal – Stony Creek Road, Textile Road
- Cut Trees – Chevrolet Street
- Drainage and Backslopes – Huron Road
- Fallen Trees – Aspen Way, Bagley Avenue, Bemis Road, Bunton Road, N Clubview Drive, Draper Avenue, Ellis Road, Martz Road, Paint Creek Drive, Red Oak Court, Red Bird Drive, Stony Creek Road, Textile Road, Tuttle Hill Road, Whittaker Road
- Limestone Patch – Morgan Road: 28 tons
- Repaired Drain – Arthur Street, Calder Street, Chevrolet Street
- Roadside Debris – E Bemis Road, Chevrolet Street, Ellis Road, Morgan Road, Mott Road, Red Oak Court
- Seed and Mulch – Glenwood Avenue, Marcus Street
- Sweeping – Textile Road

NESC Updates

Warranty work and additional equipment installation is ongoing. Northfield township zoning officials conducted a final inspection of the site and the full certificate of occupancy was granted. The security initiatives for gate controls with Electronic Security Systems, Inc. at NESC, SESC and the Main Yard gate is ongoing.

SHOP REPORT**Shop Repairs**

- Tires Repaired – 6 tires
- New Tire Installation – 6 tires
- Vehicles Serviced – 8
- Vehicles Serviced by Suburban Chevrolet – 4
- Work Orders Completed – 45

Equipment Repair

Note: The entire shop staff toured the Detroit Diesel Assembly Plant

- Loader 879 – Prepped for Heavy Equipment
- Tanker 1199 – Replaced melted plumbing
- Truck 130 – Replaced a headlamp assembly
- Truck 174 – Replaced front brakes
- Truck 240 – Replaced a rear spring
- Truck 333 – Replaced all rear suspension wear pads
- Truck 366 – Continued converting into a brine spray truck
- Truck 379 – Replaced the EGR control arm

BUILDING & GROUNDS REPORT

Yard One

- Janitorial
- Painted the fuel island and office stairway hand rails

Yard Two

- Painted the fuel island

Yard Three

- Lawn maintenance

Yard Four

- Lawn maintenance

NESC

- Installed new power washing system