



## WASHTENAW COUNTY ROAD COMMISSION

### TOWNSHIP/STAFF REPORT – November 6, 2018

For the period of October 8, 2018 thru October 28, 2018

## TOWNSHIP REPORT

---

### OPERATIONS REPORT

#### MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

#### ANN ARBOR TOWNSHIP

- Fallen Trees – Clark Road, Plymouth Road
- Limestone Patch – Ford Road, Warren Road: 38 tons
- Roadside Debris – N Maple Road
- Belgrade Notch Street Limestone Resurfacing Project – 352 tons
- Oakcleft Street Limestone Resurfacing Project – 309 tons
- Wayside Drive Limestone Resurfacing Project – 659 tons

#### AUGUSTA TOWNSHIP

- Cleaned Pipes – Butler Road
- Limestone Patch – Arkona Road, Hitchingham Road, Judd Road, Liss Road, McKean Road, Pitman Road: 170 tons
- Repair Washout – Bunton Road

#### BRIDGEWATER TOWNSHIP

- Boom Mow – Allen Road, Austin Road, Schneider Road, Wilbur Road
- Drainage and Backslopes – Austin Road, Kies Road
- Fallen Tree – Burmeister Road, Ernst Road, Hogan Road, Lima Center Road, Wallace Road
- Limestone Patch – Kies Road: 13 tons
- Limestone Patch Shoulders – Austin Road: 6 tons
- Primary Road Dust Control
- Roadside Debris – Clinton Road, McCollum Road

## DEXTER TOWNSHIP

- Boom Mow – Dexter-Pinckney Road
- Brush Removal – Anne Drive
- Fallen Trees – Hankerd Road
- Roadside Debris – Dexter-Pinckney Road
- Shoulder Maintenance – Dexter Townhall Road, Glenbrook Road, Hankerd Road, N Territorial Road

## FREEDOM TOWNSHIP

- Boom Mow – Allen Road, Kothe Road, Parker Road, Pleasant Lake Road, Schneider Road, Steinbach Road, Wilbur Road
- Fallen Trees – Ellsworth Road, Fletcher Road, Schmitz Road
- Gravel Patch – Steinbach Road: 14 tons
- Limestone Patch – S Parker Road: 28 tons
- Limestone Patch Shoulders – Pleasant Lake Road: 6 tons
- Primary Road Dust Control
- Ellsworth Road Limestone Resurfacing – 1,947 tons

## LIMA TOWNSHIP

- Pulled Shoulders – Dexter-Chelsea Road
- Huron Waterloo Loop Phase 2 – Tree Removal and Grading

## LODI TOWNSHIP

- Cleaned Pipe – Bethel Church Road
- Gravel Patch – Alber Road, Bethel Church Road, Saline Waterworks Road, Textile Road, Weber Road: 63 tons
- Limestone Patch – Dell Road, Saline Waterworks Road, Textile Road, Zeeb Road: 130 tons

## LYNDON TOWNSHIP

- Fallen Trees – Farnsworth Road
- Gravel Patch – Bush Road, Hayes Road: 12 tons
- Limestone Patch – Waterloo Road: 6 tons
- Shoulder Maintenance – Hadley Road, Island Lake Road, N Territorial Road, Stofer Road, Werkner Road

## MANCHESTER TOWNSHIP

- Boom Mow – Austin Road
- Fallen Trees – Herman Road, Mulvaney Road, Sandborn Road
- Gravel Patch – Logan Road: 28 tons
- Local Road Dust Control
- Primary Road Dust Control

## NORTHFIELD TOWNSHIP

- Boom Mow – Front Street, Lincoln Drive, Ridge Road: 19 tons
- Fallen Trees – Earhart Road, N Territorial Road, Seven Mile Road, Six Mile Road
- Limestone Patch – Joy Road, Six Mile Road: 38 tons
- Limestone Patch Shoulders – Seven Mile Road: 7 tons

#### PITTSFIELD TOWNSHIP

- Cleaned Drain – Lake Pointe Lane
- Fallen Tree – Bemis Road
- Repair Cross-Road Culvert – Golfside Drive
- Roadside Debris – Ellsworth Road

#### SALEM TOWNSHIP

- Boom Mow – Angle Road, Curtis Road, Pontiac Trail, Seven Mile Road, Six Mile Road
- Canopy Cutting – Brookville Road
- Fallen Tree – Joy Road
- Limestone Patch – Brookville Road, Five Mile Road: 42 tons
- Limestone Patch Shoulders – Eight Mile Road, Pontiac Trail – 47 tons
- Local Road Dust Control

#### SALINE TOWNSHIP

- Fallen Trees – Arkona Road, Macon Road
- Limestone Patch – Arkona Road, Case Road, Dell Road, Macon Road: 61 tons

#### SCIO TOWNSHIP

- Boom Mow – Parker Road, Zeeb Road
- Gravel Patch – Blueberry Lane, Craig Road, Deerfield Place, Delhi Road, Lakeview Avenue, Lamplighter Drive, Pheasant Drive, Stowe Street, Wagner Road: 18 tons
- Local Road Dust Control
- Street Sweeping – Liberty Road, Platt Road

#### SHARON TOWNSHIP

- Fallen Trees – Heim Road, Sharon Valley Road

#### SUPERIOR TOWNSHIP

- Chip Brush – Ridge Road
- Fallen Trees – Gotfredson Road, Hickman Road, Warren Road
- Limestone Patch – Warren Road: 8 tons
- Limestone Patch Shoulders – N Prospect Road: 2 tons
- Local Road Dust Control

#### SYLVAN TOWNSHIP

- Boom Mow – Bush Road, Conway Road, Cavanaugh Lake Road, Sibley Road, Sylvan Road
- Brush Removal – Old US-12 Road
- Limestone Patch – Conway Road: 3.5 tons

#### WEBSTER TOWNSHIP

- Boom Mow – Huron River Drive
- Limestone Patch – Huron River Drive, Strawberry Lake Road, Walsh Road: 118 tons
- Limestone Patch Shoulders – N Territorial Road: 20 tons

## YORK TOWNSHIP

- Berming – Bemis Road, Maple Road, Moon Road
- Culvert Replacement – Platt Road
- Cut Bleeders – Whispering Pines Drive
- Fallen Trees – Maple Road, Willis Road
- HMA Resurfacing – Moon Road
- Limestone Patch – Fosdick Road, Mooreville Road: 140 tons
- Roadside Debris – Whittaker Road

## YPSILANTI TOWNSHIP

- Fallen Trees – Greenside Street, Hideaway Drive, Pinewood Street
- Limestone Patch Shoulders – Merritt Road: 2 tons
- Located Failed Culvert – N Pasadena Street
- Repaired Drain – Mary Catherine Street
- Roadside Debris – Huron Road, James L Hart Parkway, Rawsonville Road, Whittaker Road
- Shoulder Maintenance – Textile Road
- Nancy Park Drainage Improvements Pipe Installation

## **NESC REPORT**

Warranty work and additional equipment installation by contractors is on-going. Working on the NESC, SESC, and Main Yard gate controls continued.

## **SHOP REPORT**

### Shop Repairs

- Tires Repaired – 3 tires
- New Tire Installation – 18 tires
- Vehicles Serviced – 5
- Vehicles Serviced by Suburban Chevrolet – 4
- Work Orders Completed – 45

### Equipment Repair

Note: Performed several electrical and hydraulic repairs

- Truck 117 – Replaced front brakes
- Truck 303 – Replaced batteries
- Truck 312 – Repaired brine pump
- Truck 320 – Repaired subframe pivot
- Truck 331 – Replaced exhaust, tarp gearbox and roof strobe light
- Truck 381 – Replaced muffler and brakes
- Truck 383 – Replaced all brakes, rear suspension torque arms, and remounted hydraulic control box
- Truck 395 and 396 – Had Truck and Trailer remove left wing assemblies

## **BUILDING & GROUNDS REPORT**

### **Yard One**

- Serviced roof top air handler
- Changed filters on rapid units
- Repaired door locks
- Fuel system repairs
- Lawn maintenance
- Repaired outside lights

### **Yard Two**

- Installed motion sensors on hallway lights in office
- Fuel system repairs
- Rapid unit service and filter change
- Door lock and card reader repair
- Repaired lights
- Installed cat 6 cable to lunch room
- Repaired salt barn roof
- Repaired

### **Yard Three**

- Serviced air compressor
- Serviced office furnace and unit heaters
- Repaired roof on salt building
- Installed outside door controls
- Lawn Maintenance

### **Yard Four**

- Repaired and upgraded outside lights to LED
- Serviced furnace and unit heaters
- Serviced air compressor
- Cut concrete bollards
- Fuel system repairs
- Lawn Maintenance

### **NESC**

- Removed old wiring to trailer at old yard
- Installed cam locks on water lines
- Make spill kit for fuel system
- Serviced office furnace
- Installed new water filter on drinking fountain
- Lawn maintenance

### **Brine Well**

- Lawn maintenance
- Serviced well
- Flushed well