



WASHTENAW COUNTY ROAD COMMISSION

TOWNSHIP/STAFF REPORT – April 2, 2019

For the period of March 11 thru March 24, 2019

TOWNSHIP REPORT

OPERATIONS REPORT

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Limestone Patch – Chalmers Drive, Ford Road, Hogback Road, Thorn Oaks Drive: 64 tons
- Limestone Patch Shoulders – Hogback Road, Dixboro Road: 4 tons

AUGUSTA TOWNSHIP

- Limestone Patch – Arkona Road, Bunton Road, Hitchingham Road, Judd Road, Liss Road, McKean Road, Pitman Road, Rosbolt Road, Sikorski Road, Talladay Road, Torrey Road, Tuttle Hill Road: 1,024 tons

BRIDGEWATER TOWNSHIP

- Cut Trees – Hogan Road
- Drainage and Backslopes – Fisk Road, Parker Road, Willow Road
- Limestone Patch – Arkona Road, Braun Road, Kies Road, Sheridan Road, Wallace Road, Willow Road: 89 tons
- Limestone Patch Shoulders – Austin Road: 3 tons

DEXTER TOWNSHIP

- Limestone Patch – Colby Road, N Dancer Road, Island Lake Road, Madden Road, McKinley Road, Riker Road, Second Street, Toma Road, Waterloo Road, Winston Road, Wylie Road: 109 tons

FREEDOM TOWNSHIP

- Boom Mow – S Parker Road
- Cut Trees – Ernst Road
- Gravel Patch – Kothe Road, S Lima Center Road, Rentz Road: 27 tons
- Limestone Patch – Bemis Road, Kothe Road, S Lima Center Road, Parker Road, Rentz Road, Waters Road: 44 tons
- Limestone Patch Shoulders – Pleasant Lake Road: 3 tons

LIMA TOWNSHIP

- Boom Mow – N Dancer Road, Easton Road, Fletcher Road, Freer Road, Gross Road, Jerusalem Road, Lima Center Road, Steinbach Road
- Built Approach Ramps – Dexter-Chelsea Border-to-Border Trail
- Culvert Installations – Dexter-Chelsea Border-to-Border Trail
- Limestone Patch – Easton Road, Dancer Road, Fletcher Road, Freer Road, Lima Center Road, McKinley Road, Peckins Road, Steinbach Road, Trinkle Road: 145 tons

LODI TOWNSHIP

- Drainage and Backslopes – Tessmer Road, Waters Road
- Gravel Patch – Dell Road, Diuble Road, Ellsworth Road, Gensley Road, Lindemann Road, Parker Road, Textile Road, Waters Road, Weber Road, Zeeb Road: 322 tons
- Limestone Patch – Dell Road, S Zeeb Road: 30 tons

LYNDON TOWNSHIP

- Limestone patch – Bowdish Road, Cassidy Road, Guinan Drive, Island Lake Road, Lindley Road, Lingane Road, Mester Road, Roepke Road, Waterloo Road, Wild Goose Lake Road: 88 tons

MANCHESTER TOWNSHIP

- Boom Mow – Herman Road, Sharon Hollow Road, Watkins Road
- Cut Trees – Logan Road
- Drainage and Backslopes – Hudson Road
- Gravel Patch – Sharon Hollow Road: 11 tons
- Limestone Patch – Buss Road, Mull Road, Noggles Road, Sharon Hollow Road, Wellwood Road: 87 tons

NORTHFIELD TOWNSHIP

- Drainage and Backslopes – Main Street
- Fallen Trees – Sutton Road
- Limestone Patch – Coyle Road, Earhart Road, Eight Mile Road, Elizabeth Street, Five Mile Road, Hellner Road, Jennings Road, Joy Road, Kearney Road, Lincoln Drive, Maple Road, Nollar Road, Six Mile Road, Seven Mile Road, Spencer Road, Walnut Drive, Winters Lane: 438 tons
- Repaired Culvert – Earhart Road
- Repaired Sinkhole – Barker Road

PITTSFIELD TOWNSHIP

- Boom Mow – Marton Road
- Limestone Patch – Campbell Road, Merritt Road, Morgan Road, Thomas Road, Warner Road: 203 tons
- Limestone Patch Shoulders – Ann Arbor-Saline Road, Ellsworth Road, Lohr Road, Maple Road, State Road: 88 tons
- Roadside Debris – Ann Arbor-Saline Road

SALEM TOWNSHIP

- Fallen Trees – Six Mile Road
- Limestone Patch – Chubb Road, N Dixboro Road, Five Mile Road, Six Mile Road: 134 tons
- Repair Culvert – Curtis Road, Tower Road

SALINE TOWNSHIP

- Limestone Patch – Braun Road, Macon Road, Mooreville Road: 168 tons
- Repaired Sinkhole – Dell Road

SCIO TOWNSHIP

- Boom Mow – Huron River Drive
- Limestone Patch – Cottontail Lane, Craig Road, E Delhi Road, Liberty Road, Luella Street, Park Road, Robinwood Drive, Scio Road, W Delhi Road: 147 tons
- Removed Damaged Guardrail – Marshall Road
- Tree Trimming – Cedar Ridge Drive, Cloverleaf Court, Red Rock Court, Redstone Court, Rockwood Court, Rollingwood Drive, Sand Rock Court, Wild Ivy Court, Wild Rose Court

SHARON TOWNSHIP

- Boom Mow – Below Road, Easudes Road, Kendall Road, Struthers Road
- Cut Trees – Sylvan Road
- Gravel Patch – Bethel Church Road, Easudes Road, Sharon Valley Road: 17 tons
- Limestone Patch – Bethel Church Road, Easudes Road, Heim Road, Meyers Road, Prospect Hill Road, Sharon Valley Road, Sylvan Road, Struthers Road, Walker Road, Washburne Road: 152 tons

SUPERIOR TOWNSHIP

- Boom Mow – Berry Road, Gotfredson Road, Warren Road
- Drainage and Backslopes – Plymouth Road
- Fallen Trees – Vreeland Road
- Limestone Patch – Cherry Hill Road, Gale Road: 98 tons
- Limestone Patch Shoulders – N Prospect Road: 2 tons
- Repair Culvert – Berry Road
- Repaired Guardrail – Plymouth Road

SYLVAN TOWNSHIP

- Drainage and Backslopes – Glazier Road
- Limestone Patch – Kilmer Road, Liebeck Road, Lowery Road, McKinley Road, Winters Road: 46 tons

YORK TOWNSHIP

- Boom Mow – Dennison Road, Judd Road, Mooreville Road, Moon Road, Saline-Milan Road, Stony Creek Road, Willis Road
- Limestone Patch – Crane Road, Judd Road, Mooreville Road: 128 tons
- Repair Washout – Willis Road

YPSILANTI TOWNSHIP

- Drainage and Backslopes – Canyon Drive, Munger Road
- Limestone Patch – Bemis Road, Ellis Road, Morgan Road, Thomas Road: 231 tons

WINTER MAINTENANCE

- Crews Responded – 4 times
- Total Salt Used – 172 tons
- Total Abrasives Used – 88 tons
- Total Brine Used – 0 gallons

NESC REPORT

Warranty work is on-going.

SHOP REPORT

Shop Repairs

- New Tire Installation – 0
- Tires Repaired – 5 tires
- Vehicles Serviced – 11
- Vehicles Serviced by Suburban Chevrolet – 5
- Work Orders Completed – 43

Equipment Repair

Note: Replaced 5 hydraulic hoses and made 7 miscellaneous electrical repairs.

- Truck 135 – Replaced the transfer tank pump
- Truck 186 – Added extra battery to the inverter system
- Truck 252 – Replaced the clutch master cylinder and pedal assembly
- Truck 327 – Resealed the steering gearbox
- Truck 344 – Replaced the radiator mounting system
- Truck 371 – Replaced the trailer plug
- Truck 374 – Replaced the exhaust stack, a wheel seal and rear brakes.

BUILDING & GROUNDS REPORT

Yard One

- Moved and assembled office furniture
- Repaired garage door for parking garage
- Cleaned out lockers in locker room
- Janitorial and recycling
- Repaired fuel system

Yard Two

- Installed new plumbing for brine pump
- Installed gutter on lean-to
- Repaired rapid unit
- Repaired plumbing in men's restroom

Yard Four

- Replaced sump pump in brine area
- Made cover for clean-out in garage

Yard Six

- Repaired garage door