

Washtenaw County Road Commission

Operations Report: 05/24/2021 thru 06/06/2021

Board Meeting Date: June 15, 2021

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

AUGUSTA TOWNSHIP

- Chipsealing – Willis Road
- Limestone Patch – Bunton Road, Country Lane, Judd Road, Macey Road, Pinehurst Drive, Rawsonville Road, Tuttle Hill Road: 155 tons

BRIDGEWATER TOWNSHIP

- Gravel Patch – Sheridan Road: 15 tons
- Limestone Patch – Allen Road, Lima Center Road, Wilbur Road, Willow Road: 72 tons
- Local Road Dust Control

DEXTER TOWNSHIP

- Brush Removal – Island Lake Road, McGregor Road
- Fallen Trees – Island Lake Road, Rainbow Drive
- Gravel Patch Shoulders – Dexter-Pinckney Road, Dexter Townhall Road: 29 tons
- Local Road Dust Control

FREEDOM TOWNSHIP

- Gravel Patch – Bethel Church Road: 25 tons
- Limestone Patch – Bethel Church Road: 12 tons
- Local Road Dust Control
- Primary Road Dust Control
- Roadside Debris – Pleasant Lake Road

LIMA TOWNSHIP

- Limestone Patch – Fletcher Road, Trinkle Road: 21 tons
- Local Road Dust Control

LODI TOWNSHIP

- Local Road Dust Control
- Primary Road Dust Control

LYNDON TOWNSHIP

- Fallen Trees – Boyce Road

- Limestone Patch – Roepke Road: 12 tons

MANCHESTER TOWNSHIP

- Fallen Trees – Allen Road, Hogan Road, Mull Road
- Gravel Patch – English Road, Grossman Road, Henzie Road, Herman Road, Mull Road: 24 tons
- Limestone Patch – Schleweis Road: 32 tons

NORTHFIELD TOWNSHIP

- Fallen Trees – Whitmore Lake Road
- Limestone Patch – Earhart Road, Eight Mile Road, Five Mile Road, Joy Road, Kearney Road, Nollar Road, Northfield Church Road, Six Mile Road, Seven Mile Road, Spencer Road, Whitmore Lake Road: 465 tons
- Roadside Debris – N Territorial Road

PITTSFIELD TOWNSHIP

- Berming – Ellsworth Road, Maple Road
- Chipsealing – Crane Road, Textile Road
- Cleaned Ditch – Bemis Road
- Cleaned Pipe – Amber Way, Crane Road, Maple Road
- Cracksealing – Affirmed Court, Cloverlane Drive, Triple Crown Court, Whirlaway Drive
- Cut Bleeders – Campbell Road, Marton Road, Morgan Road, Thomas Road
- Fallen Trees – Morgan Road, Thomas Road
- Flooding – Carpenter Road, Packard Road
- Local Road Dust Control
- Roadside Debris – Carpenter Road
- Saw Cut – Cayman Boulevard, Seminole Street

SALEM TOWNSHIP

- Limestone Patch – Brookville Road, Chubb Road, Currie Road, Dixboro Road, Five Mile Road, Salem Road, Tower Road, Weed Road: 230 tons
- Local Road Dust Control

SALINE TOWNSHIP

- Limestone Patch – Abel Road, Braun Road, Dell Road, Hack Road, Macon Road, Parker Road, Schill Road: 177 tons
- Limestone Patch Shoulders – Jordan Road, Macon Road: 30 tons
- Limestone Resurfacing Project – Mooreville Road: 8,632

SCIO TOWNSHIP

- Cut Bleeders – Park Road, Liberty Road
- Fallen Trees – Baker Road
- HMA and Aggregate Shoulder Placement – Miller Road

SUPERIOR TOWNSHIP

- Fallen Trees – Plymouth Road
- Limestone Patch – Vreeland Road: 34 tons
- Roadside Debris – Dixboro Road

SYLVAN TOWNSHIP

- Local Road Dust Control

WEBSTER TOWNSHIP

- Boom Mow – Scully Road
- Cut Trees – Scully Road
- Local Road Dust Control

YORK TOWNSHIP

- Chipsealing – Milkey Road, Moon Road, Platt Road, Saline-Milan Road, Willis Road
- Cleaned Pipes – Bemis Road
- Limestone Patch – Jewell Road, Judd Road: 60 tons
- Limestone Patch Shoulders – Carpenter Road: 60 tons
- Limestone Resurfacing Project – Mooreville Road: 3,987 tons
- Local Road Dust Control
- Street Sweeping – Saline-Milan Road

YPSILANTI TOWNSHIP

- Berming – Bemis Road, Munger Road
- Chipsealing – Stony Creek Road
- Drainage and Backslopes – Creekway Drive, Daytona Street
- Flooding – Packard Road
- Roadside Debris – Bemis Road, Merritt Road

STATE TRUNKLINE REPORT

- Guardrail Repair – I-94, M-14, US-12
- Surface Maintenance – US-12, US-23

AFTER HOURS CALL-INS

- Debris in Roadway – 15
- Fallen Trees – 9
- Plugged Drain – 1
- Road Defect – 1

SHOP REPORT

Shop Repairs

- Work Orders Completed – 35
- Tires Repaired – 2 tires
- Vehicles Serviced – 10

Equipment Repair

- Prepped New Equipment – Graders 472 & 484, Loader 875 and Sign Truck 260
- Truck 344 – Replaced water pump, repaired A/C, cleaned DOC & DPF
- Truck 381 – Replaced the carrier bearing.
- Truck 190 – Replaced the battery
- Loader 876 – De-commissioned

BUILDING & GROUNDS REPORT

Yard One

- Repaired exhaust fan in Administration Building
- Installed LED lights in green barn
- Turned on drinking fountain
- Watered landscaping
- Garage maintenance
- Sprayed for weeds
- Lawnmowing

Yard Two

- Cleaned up debris from locker project
- Installed pallet racking and wire crib
- Turned on drinking fountain
- Installed water booster pump
- Sprayed for weeds
- Lawnmowing

Yard Three

- Painted block inside and outside of parking garage
- Built and installed work bench in parking garage
- Installed wood utility work bench
- Turned on drinking fountain
- Sprayed for weeds
- Lawnmowing

Yard Four

- Painted block inside and outside of parking garage
- Replaced electrical plug on brine system
- Hung emergency sign for fuel island
- Turned on drinking fountain
- Installed door enclosure
- Sprayed for weeds
- Lawnmowing

Yard Six

- Turned on drinking fountain
- Sprayed for weeds

- Lawnmowing

Kaiser Well

- Monitored brine levels
- Adjusted well head
- Sprayed for weeds
- Lawnmowing