

## Washtenaw County Road Commission

Operations Report: 01/24/2022 thru 02/06/2022

Board Meeting Date: February 15, 2022

---

### MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

#### AUGUSTA TOWNSHIP

- Boom Mow – Rosbolt Road, Tuttle Hill Road

#### PITTSFIELD TOWNSHIP

- Boom Mow – Thomas Road
- Cut Trees – Lohr Road, Oak Valley Drive
- Roadside Debris – Golfside Road, Maple Road

#### SCIO TOWNSHIP

- Cut Trees – Maple Road, Wagner Road

#### YPSILANTI TOWNSHIP

- Boom Mow – Mott Road
- Fallen Trees – Clubview Drive, Congress Street, Huron River Drive
- Roadside Debris – Munger Road

### **STATE TRUNKLINE REPORT**

- Surface Maintenance – I-94, US-23

### **AFTER HOURS CALL-INS**

- Debris in Roadway – 6
- Damaged Guardrail – 1
- Fallen Trees – 1
- Icy Roads – 5

### **WINTER MAINTENANCE**

- Crews Responded – 11 times
- Total Salt Used – 6,998 tons
- Total Abrasives Used – 453 tons
- Total Brine Used – 20,082 gallons

## **SHOP REPORT**

### **Shop Repairs**

- Work Orders Completed – 85
- New Tire Installation – 16
- Tires Repaired – 5
- Vehicles Serviced – 3
- Service Call Runs – 4

### **Equipment Repair**

- Plow 635 – Replaced the wiring harness.
- Salter 706 & 763 – repaired flight chains.
- Truck 117 – Replaced front brakes.
- Truck 117 & 335 – Replaced the starters.
- Truck 119 – Decommissioned.
- Truck 158 & 170 – Replaced batteries.
- Truck 306 – Replaced the heating system blend door actuator.
- Truck 320 – Replaced the radiator.
- Truck 333 – Replaced the front driveshaft section.
- Truck 348 – Repaired broken circle.
- Truck 380 – Replaced trans cooler lines.
- Truck 388 – Replaced leaking ABS valves.
- Truck 399 – Replaced a brake chamber.

## **BUILDING & GROUNDS REPORT**

### **Yard One**

- Installed CAT 6 wire for board room technology upgrades
- Fixed leaks on air lines
- Repaired stockroom door
- Replaced emergency light
- Plowed parking lots and cleared sidewalks (6 days)
- Monthly building checks
- Removed trash and scrap steel

### **Yard Two**

- Repaired leak on fuel pump handle
- Monthly building checks

### **Yard Three**

- Monthly building checks

#### Yard Four

- Repaired main entry gate
- Monthly building checks

#### Yard Six

- Repaired leak on brine system fill hose
- Replaced valve on brine tank
- Repaired diesel pump handle
- Monthly building checks