

Washtenaw County Road Commission

Operations Report: 04/25/2022 thru 05/08/2022

Board Meeting Date: May 17, 2022

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Fallen Trees – Dixboro Road
- Limestone Patch – Country Club Road, Earhart Road, Englave Drive, Gleaner Hall Road, Landsdowne Road, Maple Road, Stein Road, Warren Road, Westridge Road: 106 tons

AUGUSTA TOWNSHIP

- Boom Mow – Hitchingham Road
- Limestone Patch – Hitchingham Road, Judd Road, McCrone Road, McKean Road, Tuttle Hill Road: 282 tons
- Limestone Resurfacing Project – McCrone Road: 401 tons

BRIDGEWATER TOWNSHIP

- Culvert Replacement – McCollum Road
- Fallen Trees – Austin Road
- Gravel Patch – Braun Road: 12 Tons
- Limestone Patch – Allen Road, Bemis Road, Braun Road, Hogan Road, McCollum Road, Wilbur Road: 76 ton
- Primary Road Dust Control

DEXTER TOWNSHIP

- Limestone Patch – Bass Avenue, McKinley Road: 20 tons
- Primary Road Dust Control

FREEDOM TOWNSHIP

- Gravel Patch – Bemis Road, Ellsworth Road, Ernst Road, Esch Road, Saline Waterworks Road, Steinbach Road: 51 tons
- Limestone Patch – Bemis Road, Ellsworth Road, Lima Center Road, Loeffler Road, Peckins Road, Pfaus Road, Saline Waterworks Road, Steinbach Road: 97 tons
- Local Road Dust Control
- Primary Road Dust Control

LIMA TOWNSHIP

- Drainage and Backslopes – Steinbach Road
- Gravel Patch – Lima Center Road, Sager Road: 19 tons
- Limestone Patch – Fletcher Road, Lima Center Road: 22 tons
- Primary Road Dust Control

LODI TOWNSHIP

- Limestone Patch – Alber Road, Bethel Church Road, Gensley Road, Textile Road, Weber Road: 135 tons
- Repaired Washout – Saline Waterworks Road, Wagner Road: 20 tons

LYNDON TOWNSHIP

- Fallen Trees – Waterloo Road
- Limestone Patch – Bowdish Road, Boyce Road, Cassidy Road, First Street, Goodband Road, Guinan Drive, Joslin Lake Road, Wild Goose Lake Road: 60 tons
- Shoulder Maintenance – Werkner Road: 2 tons

MANCHESTER TOWNSHIP

- Cleaned Culverts – Tracey Road
- Culvert Maintenance – Tracey Road, Van Tuyle Road: 4 tons
- Drainage and Backslopes – Sheridan Road
- Gravel Patch – Burtless Road, Fahey Road, Lemm Road, Mull Road, Schleweis Road, Sharon Hollow Road, Wolff Road: 35 tons
- Limestone Patch – Allen Road, Bowens Road, Burtless Road, Eisman Road, Fahey Road, Hieber Road, Lemm Road, Lima Center Road, Logan Road, Schleweis Road, Sharon Hollow Road, Van Tuyle Road, Wolff Road: 98 tons

NORTHFIELD TOWNSHIP

- Drainage and Backslopes – Hellner Road, Joy Road, Maple Road, Northfield Church Road
- Fallen Trees – Coyle Road
- Limestone Patch – Dixboro Road, Earhart Road, Eight Mile Road, Five Mile Road, Garfield Drive, Jennings Road, Joy Road, Kearney Road, Leland Drive, Maple Road, Nollar Road, Northfield Church Road, Rushton Road, Spencer Road, Trudy Lane, Whitmore Lake Road: 497 tons
- Roadside Debris – Whitmore Lake Road

PITTSFIELD TOWNSHIP

- Boom Mow – Crane Road
- Cleared Drain – Carpenter Road, Ellsworth Road
- Cut Trees – Bicentennial Parkway, Cody Circle, Cutler Circle, Darlington Circle, Eastwood Circle, Green Valley Drive, Gyers Meadow Lane, Harwood Circle, Hatfield Circle, Lohr Road, Rathfon Circle, Wedgewood Circle
- Fallen Trees – Morgan Road
- HMA Mill and Fill – Lohr Road
- Roadside Debris – Carpenter Road, Maple Road

SALEM TOWNSHIP

- Berming – Eight Mile Road
- Culvert Repair – Salem Farms Drive
- Drainage and Backslopes – Eight Mile Road, Salem Farms Drive
- Fallen Trees – Vorhies Road
- Limestone Patch – Dixboro Road, Five Mile Road, Joy Road, Napier Road, Tower Road, Vorhies Road: 136 tons

SCIO TOWNSHIP

- Culvert Replacement – Huron River Drive, Joy Road, Scio Church Road
- Limestone Patch – Delhi Court, Marshall Road: 33 tons
- Repaired Washout – Riverbend Drive
- HMA Mill and Fill – Huron River Drive, Scio Church Road

SHARON TOWNSHIP

- Culvert Replacement – Lehman Road
- Gravel Patch – Bethel Church Road, Hashley Road, Lamb Road, Lehman Road, Smythe Road, Sylvan Road, Waldo Road, Washburne Road, Wingate Road: 52 tons
- Limestone Patch – Bethel Church Road, Easudes Road, Grass Lake Road, Hashley Road, Lamb Road, Lehman Road, Parr Road, Sharon Valley Road, Smythe Road, Sylvan Road, Waldo Road, Washburne Road, Wingate Road: 144 tons
- HMA Mill and Fill – Pleasant Lake Road

SUPERIOR TOWNSHIP

- Culvert Failure – Gotfredson Road, Warren Road
- Limestone Patch – Berry Road, Cherry Hill Road, Frains Lake Road, Leforge Road, Vorhies Road: 257 tons

SYLVAN TOWNSHIP

- Cut Bleeders – Fahrner Road, Hayes Road, Heim Road, Hoppe Road, Kilmer Road, Notten Road
- Cut Trees – Garvey Road
- Gravel Patch – Hoppe Road, Kilmer Road, McLure Road: 32 tons
- Limestone Patch – Hoppe Road, Kilmer Road, Lingane Road, McLure Road, Spring Lake Drive: 41 tons
- Local Road Dust Control

WEBSTER TOWNSHIP

- Limestone Patch – Base Lake Drive, Daly Road, Donovan Road, Gregory Road, Huron River Drive, Joy Road, Strawberry Lake Road, Sunrise Drive, Walsh Road, Zeeb Road: 131 tons
- Local Road Dust Control
- Primary Road Dust Control
- Repaired Washout – Mast Road: 11 tons

YORK TOWNSHIP

- Berming – Petersburg Road, Platt Road
- Boom Mow – Platt Road
- Culvert Replacement – Fosdick Road, Jewell Road, Platt Road
- Cut Trees – Platt Road
- Drainage and Backslopes – Fosdick Road, Jewell Road, Petersburg Road
- Limestone Patch – Bishop Road, Covington Drive, Jewell Road, Landsend Lane, Londonderry Drive, Warner Road: 45 tons
- HMA Crush and Shape – Moon Road

YPSILANTI TOWNSHIP

- Cleaned Drains – Fall River Road, Grove Road, Laurel Avenue, Lexington Parkway, River Street
- Fallen Trees – Cypress Point Drive
- Roadside Debris – Clark Road, Devonshire Street, Stony Creek Road
- Structure Maintenance – Pine View Drive

STATE TRUNKLINE REPORT

- Surface Maintenance – I-94 Peirce rd to M-52, US-12 Saline to Clinton
- Cable Guardrail – US-23 south of I-94
- Adopt-a-Highway litter bags I-94, US-23, US-12

AFTER HOURS CALL-INS

- Damaged Guardrail – 3
- Fallen Tree – 1
- Roadside Debris – 12
- Road Defect – 5
- Water Over Road – 1

SHOP REPORT

Shop Repairs

- Work Orders Completed – 43
- New Tire Installation – 1
- Tires Repaired – 6
- Vehicles Serviced – 6
- Service Call Runs - 4

Equipment Repair

- Truck 232 – New rear brakes
- Truck 133 – New front brakes and knock sensor
- Truck 336 – Replaced right wing synchronizing valve and reinforced rear fenders
- Truck 205 – Decommissioned
- Truck 373 – Continue conversion to brine tanker truck
- 1199 – Replaced the brine spray bar actuator valve
- Truck 372 – Replaced air tanks
- Truck 172 & 176 – Replaced the batteries
- Truck 367 – Replaced the flight chain and the tarp control module

BUILDING & GROUNDS REPORT

Yard One

- Installed water manifold at hydrant
- Repaired brine area and system
- Cleaned up yard landscaping
- Replaced hitch adaptor on facilities truck
- Replaced hot water mixing valve
- Removed trash and scrap metal
- Repaired roof leaks
- Monthly building checks
- Mowed

Yard Two

- Repaired power washer
- Monthly building checks
- Cleaned up yard landscaping
- Mowed

Yard Three

- Installed hose reels
- Repaired brine tank sight tube
- Monthly building checks
- Cleaned up yard landscaping
- Mowed

Yard Four

- Replaced sump pump at brine area
- Monthly building checks
- Cleaned up yard landscaping
- Mowed

Yard Six

- Replaced gate operator motor
- Monthly building checks

Kaiser Well

- Performed well start-up activities
- Adjusted well head and water levels