

Washtenaw County Road Commission

Operations Report: 05/09/2022 thru 05/22/2022

Board Meeting Date: June 7, 2022

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Limestone Patch – Ford Road: 32 tons

AUGUSTA TOWNSHIP

- Chipseal – Whittaker Road
- Local Road Dust Control
- Primary Road Dust Control

BRIDGEWATER TOWNSHIP

- Gravel Patch – Braun Road, Kies Road, Wallace Road, Willow Road: 19 tons
- Limestone Patch – Braun Road, Hack Road, Kies Road, Wallace Road, Willow Road: 172 tons
- Primary Road Dust Control

DEXTER TOWNSHIP

- Drainage and Backslopes – Lima Center Road
- Primary Road Dust Control

FREEDOM TOWNSHIP

- Drainage and Backslopes – Hieber Road
- Fallen Trees – Bemis Road
- Limestone Patch – Kothe Road, Parker Road: 28 tons
- Local Road Dust Control

LIMA TOWNSHIP

- Boom Mow – Sager Road, Waltrous Road
- Gravel Patch – Easton Road, Steinbach Road: 27 tons
- Gravel Patch Shoulders – Old US-12, Wylie Road: 30 tons
- Limestone Patch – Fletcher Road, Trinkle Road: 86 tons

LODI TOWNSHIP

- Chipseal – Pleasant Lake Road
- Limestone Patch – Alber Road, Bethel Church Road, Clover Drive E, Clover Drive W, Ellsworth Road, Grass Road, Harvest Road, Lindemann Road, Saline Waterworks Road, Surrey Drive, Tessmer Road, Textile Road, Waters Road, Weber Road, Zeeb Road: 389 tons
- Limestone Patch Shoulders – Parker Road, Wagner Road: 17 tons
- Local Road Dust Control

LYNDON TOWNSHIP

- Culvert Replacement – Cassidy Road
- Drainage and Backslopes – Farnsworth Road, Roepke Road
- Gravel Patch – Roe Road: 7 tons
- Limestone Patch – Goodband Road, Roe Road: 40 tons
- Primary Road Dust Control

MANCHESTER TOWNSHIP

- Chipseal – Austin Road, Herman Road, Sharon Hollow Road
- Culvert Replacement – Buss Road
- Drainage and Backslopes – Austin Road, Tracey Road
- Gravel Patch – English Road, Hudson Road, Lemm Road, VanTuyle Road: 20 tons
- Limestone Patch – English Road, Mulvaney Road, Noggles Road: 58 tons
- Local Road Dust Control
- Primary Road Dust Control

NORTHFIELD TOWNSHIP

- Drainage and Backslopes – Nollar Road, Rushton Road, Six Mile Road, Sutton Road
- Fallen Trees – Spencer Road
- Limestone Patch – Brookside Drive, Earhart Road, Eight Mile Road, Five Mile Road, Hellner Road, Hillcrest Road, Joy Road, Longfellow Drive, Maple Road, Nollar Road, Northfield Church Road, Six Mile Road: 198 tons

PITTSFIELD TOWNSHIP

- Boom Mow – Thomas Road
- Chipseal – Bemis Road
- Crack Filling – Lohr Circle
- Cut Trees – Ellsworth Road
- Repair Sinkhole – Center Valley Drive, Greenside Street

SALEM TOWNSHIP

- Drainage and Backslopes – Currie Road, Eight Mile Road
- Limestone Patch – Chubb Road, Tower Road: 94 tons

SCIO TOWNSHIP

- Limestone Patch – Blueberry Lane, Burton Avenue, Cedar Ridge Drive, Cottontail Lane, Craig Road, Deerfield Place, W Delhi Road, Hickory Road, Lamplighter Drive, Laurel Hill Road, Laurentide Drive, Liberty Road, Luella Avenue, Myrtle Avenue, Park Road, Parker Road, Parkridge Drive, Pheasant Drive, Robinwood Drive, Strieter Road, Whipoorwill Lane, Woodlea Drive: 104 tons
- Limestone Resurfacing Project – Liberty Road: 1,505 tons
- HMA Mill and Resurface – Huron River Drive, Scio Church Road
- HMA Crush and Shape – Scio Church Road

SHARON TOWNSHIP

- Drainage and Backslopes – Lehman Road, Pleasant Lake Road
- Local Road Dust Control
- Gravel Resurfacing Project – Sharon Valley Road: 4,525 tons

SUPERIOR TOWNSHIP

- Limestone Patch – Harris Road, Old Prospect Road, Vreeland Road, Warren Road: 81 tons

SYLVAN TOWNSHIP

- Culvert Replacement – Cavanaugh Lake Road
- Cut Trees – Garvey Road
- Local Road Dust Control
- Primary Road Dust Control

WEBSTER TOWNSHIP

- Local Road Dust Control
- Limestone Patch – Base Lake Drive, Huron River Drive, Strawberry Lake Road: 45 tons

YORK TOWNSHIP

- Chipseal – Judd Road, Willis Road
- Drainage and Backslopes – Platt Road
- Fallen Trees – Saline-Milan Road
- Local Road Dust Control
- Primary Road Dust Control
- HMA Crush and Shape – Platt Road

YPSILANTI TOWNSHIP

- Boom Mow – Cadillac Street, Coolidge Road, Gill Street, Tyler Road, Watson Street
- Crack Filling – Centennial Avenue, Emerson Avenue, Merritt Road, Outer Lane, Pasadena Avenue, Wiard Road
- Fallen Trees – Greenside Street, Rawsonville Road
- Limestone Patch – Stony Creek Road, Textile Road: 1 ton
- Repaired Sinkhole – Southlawn Avenue
- Roadside Debris – Ford Boulevard
- Tree Trimming – Golfview Court, Golfview Drive, Greenside Street

STATE TRUNKLINE REPORT

- Surface Maintenance – I-94
- Fallen Tree – US-23

AFTER HOURS CALL-INS

- Fallen Tree – 13
- Roadside Debris – 12
- Road Defect – 2
- Water Over Road – 1

SHOP REPORT

Shop Repairs

- Work Orders Completed – 67
- New Tire Installation – 6 Tires
- Tires Repaired – 8
- Vehicles Serviced – 14
- Service Call Runs - 10

Equipment Repair

- Boom mower 1893 – Reattached deck swivel bearing
- Chip spreader 836 – Replaced conveyor belt hinges
- Loader 879 – Replaced DEF heater valve
- Truck 214 – Truck & Trailer Specialties replaced dump bed sides
- Truck 304 – Repaired flight chain
- Truck 305 – Replaced water pump had the water pump replaced.
- Truck 309 – Removed auto tire chains for the summer
- Truck 352 – Replaced tarp motor
- Truck 369 – Replaced brake chamber
- Truck 381 – Replaced suspension airbag
- Truck 396 – Replaced tarp
- Trucks 346 & 379 – Installed driveshaft carrier bearings

BUILDING & GROUNDS REPORT

Yard One

- Repaired overhead garage doors
- Repaired siding and electrical in cold storage barn
- Replaced lamps in parking garage
- Repaired plumbing in women's restroom
- Replaced brine tank site tubes
- Removed trash and scrap steel
- Repaired landscaping
- Mowed

Yard Two

- Repaired hydraulic fluid fill hose
- Replaced brine tank site tubes
- Repaired plumbing in restroom
- Cleaned fuel island
- Mowed

Yard Three

- Mowed

Yard Four

- Replaced brine tank site tubes
- Cleaned fuel island
- Mowed

Yard Six

- Repaired entry gate
- Installed new sensors on overhead garage door
- Replaced emergency back-up batteries in fire alarm panel
- Repaired plumbing in men's restroom
- Replaced brine tank site tubes
- Mowed

Kaiser Well

- Repaired plumbing for fresh water well
- Repaired electrical controls
- Adjusted fill pump packings
- Installed private property signage