

Washtenaw County Road Commission

Operations Report: 07/25/2022 thru 08/07/2022

Board Meeting Date: August 16, 2022

MAINTENANCE

Scraping of gravel roads and patching of paved roads were performed throughout the county. In addition, the following maintenance activities were performed in individual townships:

ANN ARBOR TOWNSHIP

- Limestone Patch Shoulders – Hogback Road, Huron River Drive: 21 tons

AUGUSTA TOWNSHIP

- Boom Mow – Milan Oakville Road
- Fallen Trees – Bunton Road
- Limestone Patch – Talladay Road: 2 tons

BRIDGEWATER TOWNSHIP

- Culvert Installation – Arkona Road
- Fallen Tree – Austin Road, Schellenberger Road
- Local Road Dust Control
- Primary Road Dust Control

DEXTER TOWNSHIP

- Cleaned Culvert – Riker Road
- Gravel Patch – Dexter-Pinckney Road, North Territorial Road: 3 tons
- Limestone Patch – Waterloo Road, Wylie Road: 19 tons
- Local Road Dust Control

FREEDOM TOWNSHIP

- Boom Mow – Rentz Road
- Drainage and Backslopes – Rentz Road
- Fallen Trees – Haab Road
- Fogseal – Pleasant Lake Road
- Gravel Patch – Ellsworth Road: 12 tons
- Local Road Dust Control

LIMA TOWNSHIP

- Fallen Trees – Beach Road, Dancer Road, Easton Road, Lima Center Road, Steinbach Road
- Fogseal – Parker Road
- Limestone Resurfacing Project – Dancer Road, Trinkle Road: 6,586 tons

LODI TOWNSHIP

- Fogseal – Jackson Road, Pleasant Lake Road, Zeeb Road
- Local Road Dust Control

LYNDON TOWNSHIP

- Drainage and Backslopes – Beeman Road, Cassidy Road, Osius Road
- Fallen Trees – Beeman Road, Boyce Road, Cassidy Road, Roe Road
- Gravel Patch – North Territorial Road, Waterloo Road: 7 tons
- Limestone Patch – Loveland Road: 24 tons
- Local Road Dust Control

MANCHESTER TOWNSHIP

- Boom Mow – Austin Road, Herman Road, Lake Drive North, Lake View Drive, Mull Road, Sharon Hollow Road
- Drainage and Backslopes – Grossman Road
- Fallen Trees – Austin Road
- Fogseal – Austin Road
- Gravel Patch – Grossman Road, Schleweis Road, Schwab Road, Wolff Road: 19 tons
- Limestone Patch – Grossman Road, Schleweis Road, Schwab Road: 5 tons
- Local Road Dust Control

NORTHFIELD TOWNSHIP

- Boom Mow – Leland Drive, Five Mile Road, North Territorial Road
- Drainage and Backslopes – North Territorial Road
- Limestone Patch – Eight Mile Road, Nollar Road, Six Mile Road, Spencer Road: 83 tons
- Primary Road Dust Control

PITTSFIELD TOWNSHIP

- Boom Mow – Textile Road
- Culvert Installation – Crane Road
- Cut Trees – Crane Road
- Drainage and Backslopes – Crane Road
- Fogseal – Bemis Road, Ellsworth Road, Lohr Circle, Maple Road
- Roadside Debris – Bemis Road, Maple Road, Michigan Avenue

SALEM TOWNSHIP

- Limestone Patch – Dixboro Road: 32 tons
- Local Road Dust Control

SCIO TOWNSHIP

- Fogseal – Zeeb Road
- Limestone Patch – Park Road, Staebler Road: 30 tons
- Local Road Dust Control

SHARON TOWNSHIP

- Boom Mow – Washburne Road
- Drainage and Backslopes – Sharon Valley Road, Washburne Road
- Fallen Trees – Below Road, Pleasant Lake Road
- Gravel Patch – Sylvan Road: 13 tons
- Limestone Patch – Walker Road: 18 tons

SUPERIOR TOWNSHIP

- Fallen Trees – Barrington Drive, Curtis Road, Gale Road
- Limestone Patch – First Road: 15 tons
- Limestone Patch Shoulders – Dixboro Road, Huron River Drive: 28 tons
- Local Road Dust Control

SYLVAN TOWNSHIP

- Culvert Replacement – Cavanaugh Lake Road
- Fallen Trees – McLure Road
- Limestone Patch – McLure Road: 10 tons

WEBSTER TOWNSHIP

- Culvert Replacement – Huron River Drive
- Limestone Patch – Jennings Road, Strawberry Lake Road, Walsh Road: 45 tons
- Limestone Patch Shoulders – Mast Road: 30 tons
- Local Road Dust Control

YORK TOWNSHIP

- Fogseal – Platt Road, Willis Road

YPSILANTI TOWNSHIP

- Boom Mow – Hearthside Drive, Huron River Drive, Textile Road
- Cut Trees – Wharton Street
- Cleaned Culverts – Lakeview Avenue
- Fallen Trees – Desoto Avenue, Emerson Avenue, Lamay Avenue, Textile Road, Whitman Avenue, Whittaker Road
- Limestone Patch Shoulders – Ford Boulevard, McCartney Avenue, Munger Road, Textile Road
- Roadside Debris – Bridge Road
- Structure Maintenance – Crestwood Avenue, Eugene Avenue, Seneca Street

STATE TRUNKLINE REPORT

- Surface Maintenance – US-12, M-17, M-14
- Fallen Trees – M-52, US-23
- Washout – M-14
- Guardrail – US-23

AFTER HOURS CALL-INS

- Fallen Tree – 39
- Roadside Debris – 8
- Water Over Road – 4
- Road Defect – 1

SHOP REPORT

Shop Repairs

- Work Orders Completed – 52
- New Tire Installation – 8 tires
- Tires Repaired – 5 tires
- Vehicles Serviced – 7
- Service Call Runs - 2

Equipment Repair

- Trucks 269 & 389 – Replaced the batteries
- Pickup 117 – Replaced the fuel pump
- Roller 1091 – Welded the muffler together
- Tanker 1198 – Rebuilt the brine pump

BUILDING & GROUNDS REPORT

Yard One

- Replaced photocell on security light
- Installed new door stops in parking garage
- Repaired front lobby door
- Repaired vestibule heater thermostat
- Replaced vacuum breaker in front office restroom
- Replaced water shut-off valve
- Installed new hose manifold
- Repaired service door in green barn
- Removed trash and scrap steel
- Mowed

Yard Two

- Replaced light bulbs
- Repaired water hose lines
- Repaired air lines
- Mowed

Yard Three

- Repaired damage to overhead garage door and frame
- Repaired air lines in cold storage barn
- Installed new bathroom signage
- Installed new paper towel dispenser
- Cleaned up landscaping
- Mowed

Yard Four

- Repaired water hose lines
- Installed new hose bib and hose reels
- Installed new bathroom signage
- Installed new fitting on brine fill hose
- Cleaned up landscaping
- Mowed

Yard Six

- Refilled fire pump water storage tank
- Repaired service door
- Repaired water lines
- Replaced fuel pump handle leaks
- Mowed

Kaiser Mineral Brine Well

- Painted well head
- Repaired fresh water well lines
- Repaired fill pump switch
- Filled animal burrow holes
- Cleaned up trash
- Mowed